

Facility Summary in TOOLE County in the City of GALATA

Location: FRASER OIL INC GALATA
US HIGHWAY 2 N
GALATA, MT 59444 TOOLE

Sys Fac ID: 51-02311

Last Inspected On: 12/11/2014

Operating Permit Renewal Date: 3/17/2018

Contact: James Fraser, (406) 432-2321

Owners/Operators: Fraser Oil Inc, Owner

(406)-292-3833

PO BOX 770

INVERNESS MT 59530-0770

Cory Fraser, UST Class A Operator

Cory Fraser, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
3	23	10/1/1992	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
1126			None	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		12/11/2014	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Not Listed	
1,000		12/11/2008	TLS-350/Gilbarco EMC , Veeder Root		
4	23	10/1/1992	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
1127			None	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		12/11/2014	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Not Listed	
1,000		12/11/2008	TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in TOOLE County in the City of SHELBY

Location: NOON'S 573
602 W ROOSEVELT HWY
SHELBY, MT 59474 TOOLE

Sys Fac ID: 51-00104

Last Inspected On: 9/12/2013

Operating Permit Renewal Date: 9/29/2016

Contact: H & R, Inc, (406) 452-1041

Owners/Operators: Singh Inc, Owner (406)-868-2062 ATTN HARINDER SINGH
PO BOX 7208
GREAT FALLS MT 59406-7208

S K Gasmart, Operator (406)-434-5882 602 ROOSEVELT W. HWY
SHELBY MT 59474

Harinder Singh, UST Class A Operator
Rajinder Singh, UST Class A Operator
Joe Ackerman, UST Class B Operator
Frank Kruse, UST Class B Operator
Frank Kruse, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	44	2/18/1972	Bare Steel	Steel	Flapper Valve (Auto Shutoff)
4382			Impressed Current	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		9/12/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
10,000		7/30/2014	TLS-350/Gilbarco EMC , Veeder Root	ELLD Line Tightness Testing	
2	44	2/18/1972	Bare Steel	Steel	Flapper Valve (Auto Shutoff)
3557			Impressed Current	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		9/12/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
10,000		7/30/2014	TLS-350/Gilbarco EMC , Veeder Root	ELLD Line Tightness Testing	
3	44	2/18/1972	Bare Steel	Steel	Flapper Valve (Auto Shutoff)
4383			Impressed Current	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Diesel		9/12/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
10,000		7/30/2014	TLS-350/Gilbarco EMC , Veeder Root	ELLD Line Tightness Testing	

Facility Summary in TOOLE County in the City of SHELBY

Location: MAIN STREET EXXON
101 E MAIN ST
SHELBY, MT 59474 TOOLE
Contact: Karen Robertson, (406) 434-5076

Sys Fac ID: 51-06113
Last Inspected On: 8/20/2014
Operating Permit Renewal Date: 1/8/2018

Owners/Operators: Ben Taylor Inc, Owner (800)-824-8366 PO BOX 810
SHELBY MT 59474-0810
Gregory Taylor, UST Class A Operator
Thomas Loch, UST Class B Operator
Gail Mullennax, UST Class B Operator
Gregory Taylor, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
6	26	8/16/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
426			Double-Walled	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		6/10/2015	Continuous Interstitial Monitor	Automatic Tank Gauging 0.2	
8,000			Other , Other		
7	26	8/16/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
427			Double-Walled	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		6/10/2015	Continuous Interstitial Monitor	Automatic Tank Gauging 0.2	
4,000			Other , Other		
8	26	8/16/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
428			Double-Walled	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Diesel		6/10/2015	Continuous Interstitial Monitor	Automatic Tank Gauging 0.2	
4,000			Other , Other		
9	26	8/16/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
429			Double-Walled	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Diesel		6/10/2015	Continuous Interstitial Monitor	Automatic Tank Gauging 0.2	
4,000			Other , Other		

Facility Summary in TOOLE County in the City of SHELBY

Location: SIMONS PETROLEUM INC 5108629
530 W ROOSEVELT HWY
SHELBY, MT 59474 TOOLE

Contact: (406) 434-2461

Sys Fac ID: 51-08629
Last Inspected On: 9/29/2014
Operating Permit Renewal Date: 11/27/2017

Owners/Operators: Simons Petroleum Inc, Owner (406)-434-2431 PO BOX 644
SHELBY MT 59474-0644
Pat Simons, UST Class A Operator
Joseph Pehan, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
7	10	5/27/2005	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
5014			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
6,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
8	10	5/27/2005	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
5013			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
5,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
9	10	5/27/2005	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
5012			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
6,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
10	10	5/27/2005	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
5015			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
5,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in TOOLE County in the City of SHELBY

Location: TOWN PUMP INC SHELBY
1350 W ROOSEVELT HWY
SHELBY, MT 59474 TOOLE

Sys Fac ID: 51-09749

Last Inspected On: 12/15/2015

Operating Permit Renewal Date: 4/1/2019

Contact: Trent Biggers, (460) 497-6700

Owners/Operators: Travel Plazas of Montana Inc, Owner (406)-497-6700 PO BOX 6000
BUTTE MT 59702-6000

Charles A Armstrong, UST Class A Operator
Trent Biggers, UST Class A Operator
Don Edmisten, UST Class A Operator
Daniel Sampson, UST Class A Operator
Charles A Armstrong, UST Class B Global Operator
Trent Biggers, UST Class B Global Operator
Don Edmisten, UST Class B Global Operator
Daniel Sampson, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	27	9/7/1988	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
2657			None	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Diesel		5/6/2014	Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	Yes
12,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
2	27	9/7/1988	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
2658			None	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		5/6/2014	Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
3	27	9/7/1988	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
2659			None	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		5/6/2014	Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in TOOLE County in the City of SHELBY

Location: TOWN PUMP INC SHELBY
1350 W ROOSEVELT HWY
SHELBY, MT 59474 TOOLE

Contact: Trent Biggers, (460) 497-6700

Sys Fac ID: 51-09749
Last Inspected On: 12/15/2015
Operating Permit Renewal Date: 4/1/2019

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	27	9/7/1988	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
4291			None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Safe Suction	Not Applicable
Diesel		5/6/2014	Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
5	27	9/7/1988	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
4292			None	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel		11/27/2012	Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
6	23	8/1/1992	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4293			None	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Safe Suction	Not Applicable
Diesel		11/27/2012	Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
7	23	8/1/1992	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
2663			None	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel		11/27/2012	Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
8	16	7/1/1999	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4248			Double-Walled	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel		11/27/2012	Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
8,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in TOOLE County in the City of SHELBY

Location: TOWN PUMP INC SHELBY
1350 W ROOSEVELT HWY
SHELBY, MT 59474 TOOLE

Sys Fac ID: 51-09749

Last Inspected On: 12/15/2015

Operating Permit Renewal Date: 4/1/2019

Contact: Trent Biggers, (460) 497-6700

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
9	14	10/1/2001	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4413			Double-Walled	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Not Listed	Not Applicable
Diesel		11/27/2012	Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
20,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in TOOLE County in the City of SUNBURST

Location: TAYLORS BULK PLANT
55 RAILROAD AVE
SUNBURST, MT 59482 TOOLE
Contact: (406) 937-2161

Sys Fac ID: 51-02025
Last Inspected On: 4/24/2013
Operating Permit Renewal Date: 6/22/2016

Owners/Operators: Ben Taylor Inc, Owner (800)-824-8366 PO BOX 810
SHELBY MT 59474-0810
Thomas Loch, UST Class A Operator
Gail Mullennax, UST Class A Operator
Thomas Loch, UST Class B Operator
Gail Mullennax, UST Class B Operator
Gregory Taylor, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
6	16	8/31/1999	Unknown	Flexible Plastic	
4137	Yes		None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline			Deferred	Continuous Interstitial Monitor	
12,000					
7	16	8/31/1999	Unknown	Flexible Plastic	
4138	Yes		None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline			Deferred	Continuous Interstitial Monitor	
20,000					
8	16	8/31/1999	Unknown	Flexible Plastic	
4139	Yes		None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
20,000					
9	16	8/31/1999	Unknown	Flexible Plastic	
4140	Yes		None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
20,000					

Facility Summary in TOOLE County in the City of SUNBURST

Location: TAYLORS BULK PLANT
55 RAILROAD AVE
SUNBURST, MT 59482 TOOLE
Contact: (406) 937-2161

Sys Fac ID: 51-02025
Last Inspected On: 4/24/2013
Operating Permit Renewal Date: 6/22/2016

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
10	16	8/31/1999	Unknown	Flexible Plastic	
4161	Yes		None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
1,500					

Facility Summary in TOOLE County in the City of SWEET GRASS

Location: Duty Free America's
60 3RD AVE
SWEET GRASS, MT 59484 TOOLE
Contact: Lori Schoendaller, (406) 335-2800

Sys Fac ID: 51-01377
Last Inspected On: 2/5/2015
Operating Permit Renewal Date: 3/28/2018

Owners/Operators: Duty Free America's, Owner Duty Free America's, Owner Lori Schoendaller, Operator Lori Schoendaller, UST Class A Operator Jeff Nanini, UST Class B Operator Peggy Rossmiller, UST Class B Operator Lori Schoendaller, UST Class B Operator	(406)-335-2800 (954)-986-7700	PO BOX 249 SWEET GRASS MT 59484 TAX DEPT 6100 HOLLYWOOD BLVD FL 7 HOLLYWOOD FL 33024-7983 PO BOX 249 SWEET GRASS MT 59484
---	--	---

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	26	1/1/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
871			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		1/20/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
15,000			TLS-350/Gilbarco EMC , Veeder Root		
3	26	1/1/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
872			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		1/20/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
15,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in TOOLE County in the City of SWEET GRASS

Location: MARS GAS & GROCERY
510 2ND ST
SWEET GRASS, MT 59484 TOOLE
Contact: William Cooper, (406) 424-8006

Sys Fac ID: 51-12405
Last Inspected On: 2/5/2015
Operating Permit Renewal Date: 3/27/2018

Owners/Operators: Paper Dollar Bar Inc, Owner (406)-335-2905 PO BOX 110
SWEET GRASS MT 59484-0110
Cody Young, UST Class A Operator
Cody Young, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	24	6/25/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
2718			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		2/5/2015	TLS-350/Gilbarco EMC , Veeder Root		
2	24	6/25/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
2719			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		2/5/2015	TLS-350/Gilbarco EMC , Veeder Root		